

EVIDENCE # 5A PACKAGE #5

AT&T BROADBAND  
CONVERTER TEST FORM

Date	6/13/01	Corp. #	I-COMS
Account #	69539-10	Converter #	No Serial # available
Name:	Jeff Walsh	Converter Type:	Global
Address:	6 Cooper Street	Received From:	Received from CI
City:	Taunton	State/Zip	Ma. 02780
SSN#:		Generated From:	

All Pay Channels YES All PPV Movies YES  
 Pre 4 Point Test

## CODES RECEIVED

## OTHER NOTABLE FEATURES

OUTSIDE CONVERTER APPEARANCE

P	Security Tabs Missing
I	Outside Screws Missing
R	Converter Damaged
A	Marks Around Outside Screw
T	Wires Cut
E	Tampered Codes

INSIDE CONVERTER APPEARANCE

U	ADP Module Forced Open
N	ADP Module Cover Missing
I	Scratches/Marks on Key Chips
T	Jumper Wires Still In Place
	Scratches/Marks on Legs of Key Chips
	Missing Prom #

4 Point Test

	Testing Point	Codes/Comments	Pass/Fail
1.	Check Video on converter (e.g. channel 5 or PPV barker on all channels.)	P	U
2.	Converter has 210 code or higher	I	N
3.	Converter has H-1 or H6 code, or tunes 01-99 or 01-128 consecutively.	R	I
4.	Converter does not initialize (i.e. an addressable hit)	ATE	T

Of the 4 points, how many points does it have?

Test Completed By:

Special Project Auditor Paul Marmelo

Date Completed On:

June 25, 2001

Comments:

Confirmed Pirate Device (decoder)

FOR OFFICE USE ONLY:

CONVERTER INSTALLED

BY

CONVERTER REMOVED

6-13-01

BY

CONFIDENTIAL INFORMANT

EVIDENCE # 5B PACKAGE #5

AT&T BROADBAND  
CONVERTER TEST FORM

Date	6/14/01	Corp. #	I-COMS
Account #	69539-10	Converter #	No Serial # Available
Name:	Jeff Walsh	Converter Type:	Cleartron Gold
Address:	6 Cooper St.	Received From:	Received from Mike Wood on
			6/14/01 to Lt. Warish on 6-15-01
City:	Taunton	State/Zip	Ma. 02780
SSN#:		Generated From:	

All Pay Channels YES      All PPV Movies YES  
 Pre 4 Point Test

## CODES RECEIVED

## OTHER NOTABLE FEATURES

OUTSIDE CONVERTER APPEARANCE

<u>P</u>	Security Tabs Missing
<u>I</u>	Outside Screws Missing
<u>R</u>	Converter Damaged
<u>A</u>	Marks Around Outside Screw
<u>T</u>	Wires Cut
<u>E</u>	Tampered Codes

INSIDE CONVERTER APPEARANCE

<u>U</u>	ADP Module Forced Open
<u>N</u>	ADP Module Cover Missing
<u>I</u>	Scratches/Marks on Key Chips
<u>T</u>	Jumper Wires Still In Place
<u>E</u>	Scratches/Marks on Legs of Key Chips
	Missing Prom #

4 Point Test

	Testing Point	Codes/Comments	Pass/Fail
1.	Check Video on converter (e.g. channel 5 or PPV barker on all channels.)	<u>P</u>	<u>U</u>
2.	Converter has 210 code or higher	<u>I</u>	<u>N</u>
3.	Converter has H-1 or H6 code, or tunes 01-99 or 01-128 consecutively.	<u>R</u>	<u>I</u>
4.	Converter does not initialize (i.e. an addressable hit)	<u>ATE</u>	<u>T</u>

Of the 4 points, how many points does it have?

Test Completed By:

Special Project Auditor Paul Marmelo

Date Completed On:

June 25, 2001

Comments:

Confirmed Pirate Device (decoder)

FOR OFFICE USE ONLY:

CONVERTER INSTALLED

BY

CONVERTER REMOVED

6-14-01

BY

MIKE WOOD

ACCOUNT HISTORY SUMMARY

EVIDENCE # 5C PACKAGE #5

AT&T BROADBAND  
CONVERTER TEST FORM

Date	6/20/01	Corp. #	I-COMS
Account #	43747-04	Converter #	No serial # available
Name:	Joe Amaro / Dimas Amaro	Converter Type:	Global 2600
Address:	333 Cohannet Street	Received From:	Received from William S. Jacobs on 6-20-01 to Lt. Warish on June 21, 2001
City:	Taunton	State/Zip	Ma. 02780
SSN#:		Generated From:	

All Pay Channels YESAll PPV Movies YES

Pre 4 Point Test

## CODES RECEIVED

## OTHER NOTABLE FEATURES

OUTSIDE CONVERTER APPEARANCE

P	Security Tabs Missing
I	Outside Screws Missing
R	Converter Damaged
A	Marks Around Outside Screw
T	Wires Cut
E	Tampered Codes

INSIDE CONVERTER APPEARANCE

U	ADP Module Forced Open
N	ADP Module Cover Missing
I	Scratches/Marks on Key Chips
T	Jumper Wires Still In Place
	Scratches/Marks on Legs of Key Chips
	Missing Prom #

4 Point Test

	Testing Point	Codes/Comments	Pass/Fail
1.	Check Video on converter (e.g. channel 5 or PPV barker on all channels.)	P	U
2.	Converter has 210 code or higher	I	N
3.	Converter has H-1 or H6 code, or tunes 01-99 or 01-128 consecutively.	R	I
4.	Converter does not initialize (i.e. an addressable hit)	ATE	T

Of the 4 points, how many points does it have?

Test Completed By:

Special Project Auditor Paul Marmelo

Date Completed On:

June 25, 2001

Comments:

Confirmed Pirate Device (decoder)

FOR OFFICE USE ONLY:

CONVERTER INSTALLED

BY

CONVERTER REMOVED

6-20-01

BY

WILLIAM S. JACOBS

EVIDENCE # 6A PACKAGE #6

AT&T BROADBAND  
CONVERTER TEST FORM

Date	6/21/01	Corp. #	I-COMS
Account #	43747-04	Converter #	No serial # available
Name:	Joe Amaro / Dimas Amaro	Converter Type:	Global 2600
Address:	333 Cohannet Street	Received From:	Received on 6/21/01 by Lt. P.
			Warish as result of Search
			Warrant
City:	Taunton	State/Zip	Ma. 02780
SSN#:		Generated From:	

All Pay Channels No All PPV Movies NO  
Pre 4 Point Test

## CODES RECEIVED

## OTHER NOTABLE FEATURES

OUTSIDE CONVERTER APPEARANCEINSIDE CONVERTER APPEARANCE

Security Tabs Missing	ADP Module Forced Open
Outside Screws Missing	ADP Module Cover Missing
Converter Damaged	Scratches/Marks on Key Chips
Marks Around Outside Screw	Jumper Wires Still In Place
Wires Cut	Scratches/Marks on Legs of Key Chips
Tampered Codes	Missing Prom #

4 Point Test

	Testing Point	Codes/Comments	Pass/Fail
1.	Check Video on converter (e.g. channel 5 or PPV barker on all channels.)		
2.	Converter has 210 code or higher		
3.	Converter has H-1 or H6 code, or tunes 01-99 or 01-128 consecutively.		
4.	Converter does not initialize (i.e. an addressable hit)		

Of the 4 points, how many points does it have?

Test Completed By:

Special Project Auditor Paul Marmelo

Date Completed On:

June 25, 2001

Comments:

FOR OFFICE USE ONLY:

CONVERTER INSTALLED

BY

CONVERTER REMOVED

6-21-01

BY

TAUNTON POLICE DEPARTMENT

EVIDENCE # 6B PACKAGE #6

AT&T BROADBAND  
CONVERTER TEST FORM

Date	6/21/01	Corp. #	I-COMS
Account #	43747-04	Converter #	No serial # available
Name:	Joe Amaro / Dimas Amaro	Converter Type:	Global 2600
Address:	333 Cohannet Street	Received From:	Received on 6/21/01 by Lt. P.
			Warish as result of Search
			Warrant
City:	Taunton	State/Zip	Ma. 02780
SSN#:		Generated From:	

All Pay Channels NO All PPV Movies NO  
Pre 4 Point Test

## CODES RECEIVED

## OTHER NOTABLE FEATURES

OUTSIDE CONVERTER APPEARANCEINSIDE CONVERTER APPEARANCE

Security Tabs Missing	ADP Module Forced Open
Outside Screws Missing	ADP Module Cover Missing
Converter Damaged	Scratches/Marks on Key Chips
Marks Around Outside Screw	Jumper Wires Still In Place
Wires Cut	Scratches/Marks on Legs of Key Chips
Tampered Codes	Missing Prom #

4 Point Test

	Testing Point	Codes/Comments	Pass/Fail
1.	Check Video on converter (e.g. channel 5 or PPV barker on all channels.)		
2.	Converter has 210 code or higher		
3.	Converter has H-1 or H6 code, or tunes 01-99 or 01-128 consecutively.		
4.	Converter does not initialize (i.e. an addressable hit)		

Of the 4 points, how many points does it have?

Test Completed By:

Special Project Auditor Paul Marmelo

Date Completed On:

June 25, 2001

Comments:

FOR OFFICE USE ONLY:

CONVERTER INSTALLED

BY

CONVERTER REMOVED

6-21-01

BY

TAUNTON POLICE DEPARTMENT

EVIDENCE # 6C PACKAGE #6

AT&T BROADBAND  
CONVERTER TEST FORM

Date	6/21/01	Corp. #	I-COMS
Account #	43747-04	Converter #	No serial # available
Name:	Joe Amaro / Dimas Amaro	Converter Type:	Global 2600
Address:	333 Cohannet Street	Received From:	Received on 6/21/01 by Lt. P. Warish as result of Search Warrant
City:	Taunton	State/Zip	Ma. 02780
SSN#:		Generated From:	

All Pay Channels NO All PPV Movies NO  
Pre 4 Point Test

## CODES RECEIVED

## OTHER NOTABLE FEATURES

OUTSIDE CONVERTER APPEARANCE

Security Tabs Missing  
Outside Screws Missing  
Converter Damaged  
Marks Around Outside Screw  
Wires Cut  
Tampered Codes

INSIDE CONVERTER APPEARANCE

ADP Module Forced Open  
ADP Module Cover Missing  
Scratches/Marks on Key Chips  
Jumper Wires Still In Place  
Scratches/Marks on Legs of Key Chips  
Missing Prom #

4 Point Test

	Testing Point	Codes/Comments	Pass/Fail
1.	Check Video on converter (e.g. channel 5 or PPV barker on all channels.)		
2.	Converter has 210 code or higher		
3.	Converter has H-1 or H6 code, or tunes 01-99 or 01-128 consecutively.		
4.	Converter does not initialize (i.e. an addressable hit)		

Of the 4 points, how many points does it have?

Test Completed By:

Special Project Auditor Paul Marmelo

Date Completed On:

June 25, 2001

Comments:

FOR OFFICE USE ONLY:

CONVERTER INSTALLED

BY

CONVERTER REMOVED

6-21-01

BY

TAUNTON POLICE DEPARTMENT

EVIDENCE # 6D PACKAGE #6

AT&T BROADBAND  
CONVERTER TEST FORM

Date	6/21/01	Corp. #	I-COMS
Account #	43747-04	Converter #	No serial #A available
Name:	Joe Amaro / Dimas Amaro	Converter Type:	Global 2600
Address:	333 Cohannet Street	Received From:	Received on 6/21/01 by Lt. P. Warish as result of Search Warrant
City:	Taunton	State/Zip	Ma. 02780
SSN#:		Generated From:	

All Pay Channels YES      All PPV Movies YES  
**Pre 4 Point Test**

**CODES RECEIVED****OTHER NOTABLE FEATURES**Screw missing for box cover

<b>OUTSIDE CONVERTER APPEARANCE</b>		<b>INSIDE CONVERTER APPEARANCE</b>	
<u>P</u>	Security Tabs Missing	<u>U</u>	ADP Module Forced Open
<u>I</u>	Outside Screws Missing	<u>N</u>	ADP Module Cover Missing
<u>R</u>	Converter Damaged	<u>I</u>	Scratches/Marks on Key Chips
<u>A</u>	Marks Around Outside Screw	<u>T</u>	Jumper Wires Still In Place
<u>T</u>	Wires Cut		Scratches/Marks on Legs of Key Chips
<u>E</u>	Tampered Codes		Missing Prom #

**4 Point Test**

	<b>Testing Point</b>	<b>Codes/Comments</b>	<b>Pass/Fail</b>
1.	Check Video on converter (e.g. channel 5 or PPV barker on all channels.)	<u>P</u>	<u>U</u> <u>N/A</u>
2.	Converter has 210 code or higher	<u>I</u>	<u>N</u> <u>N/A</u>
3.	Converter has H-1 or H6 code, or tunes 01-99 or 01-128 consecutively.	<u>R</u>	<u>I</u> <u>N/A</u>
4.	Converter does not initialize (i.e. an addressable hit)	<u>ATE</u>	<u>T</u> <u>N/A</u>

Of the 4 points, how many points does it have? N/A

Test Completed By: Special Project Auditor Paul Marmelo

Date Completed On: June 25, 2001

Comments: Confirmed Pirate Device (decoder)

**FOR OFFICE USE ONLY:**

<i>CONVERTER INSTALLED</i>	<i>BY</i>
<i>CONVERTER REMOVED</i>	<i>BY</i>
<u>6-21-01</u>	<u>TAUNTON POLICE DEPARTMENT</u>

EVIDENCE # 6E PACKAGE #6

AT&T BROADBAND  
CONVERTER TEST FORM

Date	6/21/01	Corp. #	I-COMS
Account #	43747-04	Converter #	No serial #A available
Name:	Joe Amaro / Dimas Amaro	Converter Type:	Global 2600
Address:	333 Cohannet Street	Received From:	Received on 6/21/01 by Lt. P.
City:	Taunton	State/Zip	Warish as result of Search
SSN#:		Generated From:	Warrant

All Pay Channels YES All PPV Movies YES  
 Pre 4 Point Test

## CODES RECEIVED

## OTHER NOTABLE FEATURES

Screw missing for box cover

OUTSIDE CONVERTER APPEARANCE		INSIDE CONVERTER APPEARANCE	
<u>P</u>	Security Tabs Missing		ADP Module Forced Open
<u>I</u>	Outside Screws Missing	<u>U</u>	ADP Module Cover Missing
<u>R</u>	Converter Damaged	<u>N</u>	Scratches/Marks on Key Chips
<u>A</u>	Marks Around Outside Screw	<u>I</u>	Jumper Wires Still In Place
<u>T</u>	Wires Cut	<u>T</u>	Scratches/Marks on Legs of Key Chips
<u>E</u>	Tampered Codes		Missing Próm #

4 Point Test

	Testing Point	Codes/Comments	Pass/Fail
1.	Check Video on converter (e.g. channel 5 or PPV barker on all channels.)	<u>P</u>	<u>U</u> N/A
2.	Converter has 210 code or higher	<u>I</u>	<u>N</u> N/A
3.	Converter has H-1 or H6 code, or tunes 01-99 or 01-128 consecutively.	<u>R</u>	<u>I</u> N/A
4.	Converter does not initialize (i.e. an addressable hit)	<u>ATE</u>	<u>T</u> N/A

Of the 4 points, how many points does it have?

N/A

Test Completed By:

Special Project Auditor Paul Marmelo

Date Completed On:

June 25, 2001

Comments:

Confirmed Pirate Device (decoder)

FOR OFFICE USE ONLY:

CONVERTER INSTALLED

BY

CONVERTER REMOVED

6-21-01

BY

TAUNTON POLICE DEPARTMENT

EVIDENCE # 6F PACKAGE #6

AT&T BROADBAND  
CONVERTER TEST FORM

Date	6/21/01	Corp. #	I-COMS
Account #	43747-04	Converter #	No serial # available
Name:	Joe Amaro / Dimas Amaro	Converter Type:	Global 2600
Address:	333 Cohannet Street	Received From:	Received on 6/21/01 by Lt. P.
City:	Taunton	State/Zip	Warish as result of Search
SSN#:		Generated From:	Warrant
All Pay Channels <u>NO</u>		All PPV Movies <u>NO</u>	
Pre 4 Point Test			

## CODES RECEIVED

## OTHER NOTABLE FEATURES

OUTSIDE CONVERTER APPEARANCE

- \_\_\_\_ Security Tabs Missing
- \_\_\_\_ Outside Screws Missing
- \_\_\_\_ Converter Damaged
- \_\_\_\_ Marks Around Outside Screw
- \_\_\_\_ Wires Cut
- \_\_\_\_ Tampered Codes

INSIDE CONVERTER APPEARANCE

- \_\_\_\_ ADP Module Forced Open
- \_\_\_\_ ADP Module Cover Missing
- \_\_\_\_ Scratches/Marks on Key Chips
- \_\_\_\_ Jumper Wires Still In Place
- \_\_\_\_ Scratches/Marks on Legs of Key Chips
- \_\_\_\_ Missing Prom #

4 Point Test

	Testing Point	Codes/Comments	Pass/Fail
1.	Check Video on converter (e.g. channel 5 or PPV barker on all channels.)		
2.	Converter has 210 code or higher		
3.	Converter has H-1 or H6 code, or tunes 01-99 or 01-128 consecutively.		
4.	Converter does not initialize (i.e. an addressable hit)		

Of the 4 points, how many points does it have?

Test Completed By:

Special Project Auditor Paul Marmelo

Date Completed On:

June 25, 2001

FOR OFFICE USE ONLY:

CONVERTER INSTALLED

BY

CONVERTER REMOVED

6-21-01

BY

TAUNTON POLICE DEPARTMENT

EVIDENCE # 6G PACKAGE #6

AT&T BROADBAND  
CONVERTER TEST FORM

Date	6/21/01	Corp. #	I-COMS
Account #	43747-04	Converter #	1000071772146
Name:	Joe Amaro / Dimas Amaro	Converter Type:	Millennium 3
Address:	333 Cohannet Street	Received From:	Received on 6/21/01 by Lt. P. Warish as result of Search Warrant
City:	Taunton	State/Zip	Ma. 02780
SSN#:		Generated From:	

All Pay Channels	<u>YES</u>	All PPV Movies	<u>YES</u>
------------------	------------	----------------	------------

Pre 4 Point Test

## CODES RECEIVED

## OTHER NOTABLE FEATURES

OUTSIDE CONVERTER APPEARANCE		INSIDE CONVERTER APPEARANCE	
<u>P</u>	Security Tabs Missing		ADP Module Forced Open
<u>I</u>	Outside Screws Missing	<u>U</u>	ADP Module Cover Missing
<u>R</u>	Converter Damaged	<u>N</u>	Scratches/Marks on Key Chips
<u>A</u>	Marks Around Outside Screw	<u>I</u>	Jumper Wires Still In Place
<u>T</u>	Wires Cut	<u>T</u>	Scratches/Marks on Legs of Key Chips
<u>E</u>	Tampered Codes		Missing Prom #

4 Point Test

	Testing Point	Codes/Comments	Pass/Fail
1.	Check Video on converter (e.g. channel 5 or PPV barker on all channels.)	<u>P</u>	<u>U</u>
2.	Converter has 210 code or higher	<u>I</u>	<u>N</u>
3.	Converter has H-1 or H6 code, or tunes 01-99 or 01-128 consecutively.	<u>R</u>	<u>I</u>
4.	Converter does not initialize (i.e. an addressable hit)	<u>ATE</u>	<u>T</u>

Of the 4 points, how many points does it have?

Test Completed By:

Special Project Auditor Paul Marmelo

Date Completed On:

June 25, 2001

Comments:

Confirmed Pirate Device (decoder)

FOR OFFICE USE ONLY:

CONVERTER INSTALLED

BY

CONVERTER REMOVED

6-21-01

BY

TAUNTON POLICE DEPARTMENT